

# SAFETY ALERT



**Safety Alert No. 411**

**February 9, 2021**


**Contact: David Nedorostek**

**Phone: (703) 787-1029**

## **Electrical Fire Damages Equipment in Motor Control Center**

An electrical fire occurred in the Motor Control Center (MCC) on an offshore production platform when an electrician engaged the circuit breaker for a Pipeline Pump motor. While checking the operation of motor #3, the electrician engaged the breaker and immediately heard crackling inside the MCC breaker cabinet<sup>1</sup>. The electrician went to disengage the breaker and heard a pop inside the cabinet as he turned it off, resulting in a platform power shutdown.

As the electrician opened the MCC breaker cabinet, he smelled smoke and saw a ½” flame under the control transformer. He immediately used a fire extinguisher to extinguish the flame and instinctively removed the breaker cabinet's fuses and resistors to prevent any other possible flare-up and to eliminate all possible connectivity within the MCC breaker cabinet. He also performed a Lockout/Tagout by placing a lock on the breaker arm to ensure no power could circulate.



*Damaged Bus Bar Bolts*

*Damaged Bus*

*Damaged transformer*

---

<sup>1</sup> Motor Control Center (MCC) cabinets are metal enclosures that house components such as variable frequency drives, motor starters, resistors, contactors, circuit breakers, fuses, disconnect switches, and overload relays. They play a very important role in the industrial power control and distribution systems.

## Analysis of the Incident

- Three bolts/nuts on the bus bar<sup>2</sup> connecting the breaker to the bus straps were either loose or damaged prior to energizing the circuit. This resulted in the bus bar heating up the circuit and causing an overload of current on the transformer. Additionally, the bolts/nuts had not been inspected recently to determine if they had been properly torqued or damaged prior to operation.
- Insulation on the bus bar behind the breaker showed signs of significant dust build-up as evidenced by visible electrical surface track<sup>3</sup> marks. This dust likely caused an electric arc.
- Insulation was damaged on two wire connections that travel from the breaker/bus bar to the control voltage transformer.

**Therefore, BSEE recommends that operators and contractors consider the following:**

- Establish inspection and maintenance policies/procedures to include:<sup>4</sup>
  - Scheduling the examination of electrical systems;
  - Conducting an infrared or thermographic inspection<sup>5</sup> in accordance with manufacturer's recommendations, and document this inspection;
  - Measuring insulation resistance and testing polarization index before an MCC is re-energized (after installation or regular maintenance);
  - Examining all barriers/insulators and replace any that show signs of arcing damage, tracking, excessive heat, or cracking;
  - Inspecting all power and control wiring, replacing any wire that has worn insulation or shows signs of overheating or cracking;

---

<sup>2</sup> A **bus bar** is a metallic strip or bar (typically copper, brass or aluminum) that conducts electricity within a switchboard, distribution board, substation, battery bank, or other electrical apparatus. Its main purpose is to conduct a substantial current of electricity, and not to function as a structural member.

<sup>3</sup> **Electrical surface tracking** is a phenomenon where an electric current burns the top layer of an insulation material and allows the current to migrate across the insulation and ultimately cause damage. Electrical surface tracking is defined as the number of seconds that a material resists the formation of a surface conducting path when subjected to an intermittent arc of high voltage and low current characteristics.

<sup>4</sup> Per **API 14F, Annex A** which describes inspection intervals for equipment; and 2<sup>nd</sup> Tier reference document **NFPA 70B**, titled, Recommended Practice for Electrical Equipment Maintenance.

<sup>5</sup>**Infrared or Thermographic inspections** are beneficial in reducing electrical failures by identifying potentially dangerous conditions such as, loose or dirty connections, overloaded or imbalanced circuits, or improperly installed equipment. By measuring the heat imbalance relative to the environment and surrounding equipment, abnormal or adverse conditions can be uncovered that if left unattended would worsen to the point of failure.

- Develop a quality control policy/procedure that provides guidance for inspection/maintenance that specifically addresses potential electrical issues, including dust accumulation on the bus bar;
- Ensure bolts/nuts are properly torqued to the Original Equipment Manufacturer specifications and inspect them for damage prior to energizing the circuit;
- Document all repair and/or replacement of electrical components. When changes are made to the electrical distribution system, update and distribute all applicable drawings and maintenance schedules to reflect the changes; and,
- Examine all bus bars and connectors, and replace any parts that are badly discolored, corroded, pitted, etc. Establish a replacement schedule for parts subjected to excessive temperatures.

--BSEE--

A **Safety Alert** is a tool used by BSEE to inform the offshore oil and gas industry of the circumstances surrounding a potential safety issue. It also contains recommendations that could assist avoiding potential incidents on the Outer Continental Shelf.

Categories: Arc Flash; Fire; Power Outage